Work Orde												Page 1
Revision ID: Item Name:	D3535-35 Wearshoe 10/14/2010	Start Qty: 8.00 Req'd Qty: 8.00		Accept	Cust Item	IĐ:			Setup	Start Stop		
Reference:	10/22/2010	Key a Qty. 8.00			Customer:			ĺ			1 1001656 00	1116 (2) 1181 (BB)
Approvals:	Process Pla	n:/	Date! 0-10-14	Tooling:	D	ate:			Run	Start		
	QC:		Date:	_ SPC (Y/N):	D	Pate:				Stop		
Sequence ID/ Work Center ID		Operation Description	***************************************	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Acce _l Qty	ot Rej Qty		Reject Number	Insp. Stamp
Draw Nbr	Rev	ision Nbr										
D3535	Rev	В								i		
100 Waterjet		FLOW WATER JET	·	0.00				B	10 =(c	<u> </u>	}	
FLOW CNC Waterjet		Memo 1-Cut as p Deburr if	per Dwg D3535 □Dwg Ro necessary	ev: □Prog Rev:	□2-						<u> </u>)
		QC2- Inspect parts off	machine FAI/FAIB	0.00								
QC Quality Control		Мето		0.00					<u>.10-10</u>	<u>s -14</u>		
120		QC8- Inspect parts - so	econd check	0.00				Į	8			Aug 10:15
QC		Memo	5H-U3	0.00								1 101011
Quality Control		F	11272									

Dart Aerospace Ltd

W/O:			WC	ORK ORDER CH	IANGES					-
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
										ı
										ı
Part No	:	PAR #:	Fault Cate	gory:	NCI	R: Yes	No DQ	A:	Date:	
	R	esolution:	Dispositio	n:	QA:	N/C Clo	sed:		Date:	
NCR:			WORK ORD	ER NON-CONFO	ORMANCE	(NCR)			
DATE	STEP	Description of NC		Corrective Action	Section B		Verific	cation	Approvai	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Descri	ption	Sign & Date		ion C	Chief Eng	QC Inspector
II										
		·								

Work Orde Thursday, Octob		•											Page 2
	D3535-35 Wearshoe 10/14/2010 10/22/2010	Start Qty: 8.00 Req'd Qty: 8.00			Accept	Cust Item Customer:	ID:			Setup	Start Stop		
Approvals:		n:			_)ate:			Run	Start Stop		
Sequence ID/ Work Center II 130 Brake NC Brake NC	•		DT8326.□3-	-Identify as D	Set Up/ Run Hours 0.00 0.00 se as per Dwg D3535 usi 3535-35.	Tool ID	Tool#	Plan Code	Accer Oty	ot Rej Qty	y	Reject Number	Insp. Stamp
QC Quality Control 150 Powdercoat Powder Coating		Memo Grey Sandtex(Ref.4.3.5.6) Millor Start Times	3 3	8:35	0.00 0.00 0.00 COVEN TEMPERATU				3				160.1020

W/O:			W	ORK ORDER CHANG	ES			. , ,	
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	D	ate Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								1100 1119	
		,							
11 111									
Part No	:	PAR #:	Fault Ca	tegory:	_ NCR: Ye	s No	DQA:	Date:	
	R	esolution:	Disposit	ion:	_ QA: N/C	Close	ed:	Date: _	
NCR:			VORK OR	DER NON-CONFORMA	NCE (NO	CR)			
DATE	STEP	Description of NC		Corrective Action Secti			Verification	Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sig Da	n & ite	Section C	Chief Eng	QC Inspector
•									
1	1			1		l	•	1	

Work Orde Thursday, Octob												Page 3
Item ID: Revision ID: Item Name: Start Date:	D3535-35 Wearshoe 10/14/2010	Start Qty: 8.00		Accept	Cust Item I				Setup	Start Stop		
Required Date: Reference:	10/22/2010	Req'd Qty: 8.00			Customer:		_		Run	Start		
Approvals:		in:	Date:	Tooling: SPC (Y/N):		nte:			Kun	Stop		
Sequence ID/ Work Center II 160 QC Quality Control)	Operation Description QC3- Inspect Part Finish Memo		Set Up/ Run Hours 0.00	Tool ID	Tool#	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
170 Packaging Packaging		Identify as per dwg & Stoo Memo	ck Location	52/8 0.00 BD 0.00	10-10 - F)Q		8,				
180 QC Quality Control		QC21- Final Inspection - 'Memo	Work Order I	0.00 0.00					- <u>-</u>		10 1 MF	0/229

W/O:			W	ORK ORDER CHANGE	S				
DATE	STEP	PRO	DCEDURE CHA	INGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA	A:	Date:	
	R	esolution:	Disposition	n:	QA: N/C Cl	osed:		Date: _	
NCR:		·	WORK ORD	ER NON-CONFORMA	NCE (NCR)			
		Description of NO		Corrective Action Section	n B	1			
DATE	STEP	Description of NC	1 10 1	A - At D		→ Verific		Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verific Section		Approval Chief Eng	Approval QC Inspector
DATE	STEP	Section A			Sign &				
DATE	STEP	Section A			Sign &				
DATE	STEP	Section A			Sign &				
DATE	STEP	Section A			Sign &				
DATE	STEP	Section A			Sign &				
DATE	STEP	Section A			Sign &				
DATE	STEP	Section A			Sign &				
DATE	STEP	Section A			Sign &				

Picklist Print

Thursday, October 14, 2010 12:41:21 PM

Work Order ID: 62969

Parent Item:

D3535-35

Parent Item Name: Wearshoe



Start Date: 10/14/2010

Required Date: 10/22/2010

Page 1

Start Qty: 8.00

Required Qty: 8.00

Co			
• •	mn	1en	116.

IPP Rev:A New Issue 07-02-15 JLM

IPP Rev:B As per Rev B 07-08-31 JLM

Verified By:EC


Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304S20GA		Purchased	No			100	sf	108.6987	0.8022	6.755368			
304/316 .040 Sheet											31070	-19	
				Location	1	Loc	Oty	Loc Code	Ì			\nearrow	
				MAT		85.9	9522		_			(2)	
					114574	10.6	6522		! _				
					115762		75.3]	15762			
				MAT20		22.3	7465						
					112885	2.	7475		i I				
					113062	. 0	.699		-				
					115440		193		-				

W/O:			V	ORK ORDER CHANGE	ES				
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
- <u></u> -								1 roa wg	
									İ
						E .			
Part No	:	PAR #:	Fault Ca	tegory:	NCR: Yes	s No DG	A:	Date: _	
	R	esolution:	Disposit	ion:	_ QA: N/C	Closed:		Date: _	
NCR:		, V	ORK OR	DER NON-CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC		Corrective Action Section		Verif	ication	Approvai	Approval
	0.1.	Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Dat		tion C	Chief Eng	QC Inspector
<u> </u>									

DART AEROSPACE LTD	Work Order:			
Description: Wearshoe	Part Number:	D3535-35		
Inspection Dwg: D3535 Rev: B		Page 1 of 1		

		FIRST AF	RTICLE INSP	ECTION	CHECKL	_IST		
		X	First Article	F	Prototyp	е		
Drav Dime	_	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Co	omments
2.0	000	+/-0.010	2.600	7		V 1B02		
1.8	885	+/-0.010	1.888	X		V		
6.0	00	+/-0.030	6.000	0		T 1801		
6.7	75	+/-0.030	6.750	<u>ح</u>		7		
Ø0.	188	+0.005/-0.001	,193	يز		V		
23.2	250	+/-0.010	23,756	L		7		
19.7	750	+/-0.010	19.750	٧		T		
17.7	750	+/-0.010	17.750	>		T		
14.2	250	+/-0.010	14.750	æ		7		
9.5	500	+/-0.010	4.500	8/		7		
4.7	'50	+/-0.010	4.750	*	*	1		
0.3	00	+/-0.010	.365	&		V		
0.3	300	+/-0.010	306	k		V		
0.0	38	+/-0.010	1037	£		V		
				1				
Measur	ed by: ្រូ	A	udited by:	//	Pro	totype Appro	val:	N/A
		0-10-19	Date:	10.10.19		Da	ate:	N/A
Rev A	Date 07.05.10	Change New Issue				Revise KJ/JLN	ed by	Approved

W/O:			W	ORK ORDER CHANG	ES			
DATE	STEP	PF	ROCEDURE CHA	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				W-21			1 100 Wg	
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes N	lo DQA:	Date: _	
	R	esolution:	Dispositio	n:	_ QA: N/C Clo	sed:	Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NCR)			
DATE	STEP	Description of NC		Corrective Action Section		Verification	Approval	Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
					İ			1
						·		





Dart Ae	rospace	e Ltd		•					
W/O:			W	ORK ORDER CHANGE	S		· 		;
DATE STEP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			, 100, 90, 100,						
Part No):	PAR #:	Fault Cat	tegory:	NCR: Yes	No DQ A	.:	Date:	
	R	esolution:	Dispositi	QA: N/C Closed: Date:					
NCR:		V	VORK ORI	DER NON-CONFORMAN	ICE (NCF	R)			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	B Sign & Date	Verific Section		Approval Chief Eng	Approval QC Inspector
	-								
	1				1				

W/O:			W	ORK ORDER CHANGE	ES	···	····	
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
-			_ .					
	}			the state of the s				<u> </u>
Part No		PAR #:						
	R	esolution:					Date: _	
NCR:		1	WORK ORD	ER NON-CONFORMA	NCE (NCR))		!
DATE	STEP	Description of NC		Corrective Action Section		Verification	1 Approval	Approval
	-	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
						,		
						·		

W/O:			W	ORK ORDER CHANGE	S				
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								,	
Part No	:	PAR #:	Fault Cat	egory:	NCR: Yes	No DQ	A :	Date:	
	R	esolution:	Dispositi	on:	QA: N/C C	losed:		Date: _	
NCR:		\	NORK OR	DER NON-CONFORMAN	ICE (NC	R)			
DATE	STEP	Description of NC		Corrective Action Section			cation	Approval	Approval
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	B Sign Date	& Sect	cation ion C	Approval Chief Eng	Approval QC Inspector
DATE	STEP	Description of NC Section A		Action Description	Sign	& Sect			Approval QC Inspector
DATE	STEP	Description of NC Section A		Action Description	Sign	& Sect			Approval QC Inspector
DATE	STEP	Description of NC Section A		Action Description	Sign	& Sect			QC Inspector
DATE	STEP	Description of NC Section A		Action Description	Sign	& Sect			QC Inspector
DATE	STEP	Description of NC Section A		Action Description	Sign	& Sect			QC Inspector
DATE	STEP	Description of NC Section A		Action Description	Sign	& Sect			QC Inspector
DATE	STEP	Description of NC Section A		Action Description	Sign	& Sect			QC Inspector
DATE	STEP	Section A		Action Description	Sign	& Sect			QC Inspector







캪

DOCUMENT

ភ

Copyright © 2006 by DART AEROSPACE USA, INC.

PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

PURPOSE


ဝ္က

COPIED

1) MATERIAL: AISI 304/316 SS SHEET PER AMS 5513 OR AMS 5524, 20 GAUGE (0.038 THICK)
(REF DART SPEC M304S20GA)
2) FINISH: POWDER COAT GREY SANDTEX (4.3.5.6) PER

D3535-31 BEND DETAIL

- QSI 005 4.3
- 3) PART IS SYMMETRICAL ABOUT &
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 5) ALL DIMENSIONS ARE IN INCHES
- 6) BREAK ALL SHARP EDGES TO 0.010 MAX
- IDENTIFY WITH DART P/N USING WHITE FINE POINT PAINT MARKER
- 8) SEE PAGE 7 FOR DETAILS AND SECTION



WEARSHOE 1:10		07 04 17
TITLE SCALE		DATE
D3535 SHEET 4 OF 7	1	
DRAWING NO. REV. B	APPROVED if	CHECKED //
PORT HADLOCK, WA	m	40
DART AEROSPACE USA, INC.	DRAWN BY	DESIGN 7

Dart Aerospa	ace	Ltd
--------------	-----	-----

W/O:		WORK ORDER CHANG								
DATE	STEP	PRO	CEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
										ļ
Part No	•	PAR #:	Fault Cat	egory:	NCF	R: Yes N	o DQA:		_ Date: _	
	R	esolution:	on: Disposition: QA			N/C Clos	sed:		Date:	
NCR:		V	VORK ORI	DER NON-CONFO	RMANCE	(NCR)				
DATE	STEP	Description of NC		Corrective Action	Section B	Ciam 0	Verifica		Approval	Approval
		Section A	Initial Chief Eng	Action Descript Chief Eng	ion	Sign & Date	Section	C	Chief Eng	QC Inspector
		·								
						•				
								٠		
					-					
· Ľ										
		. *	1				1		}	

DILLIPSI

たた




DATE 07.04.17

CHECKED

WEARSHOE

1:10


切



D3535-35 BEND DETAIL

AISI 304/316 SS SHEET PER AMS 5513 OR AMS 5524.

Wo agale 9






20 GAUGE (0.038 THICK)

1) MATERIAL:

- 5) ALL DIMENSIONS ARE IN INCHES 6) BREAK ALL SHARP EDGES TO 0.010 MAX
- IDENTIFY WITH DART P/N USING WHITE FINE POINT PAINT MARKER
- 8) SEE PAGE 7 FOR DETAILS AND SECTION



	+	APPROVED 1/	AH
ווורב	D3535	DRAWING NO.	PORT HADLOCK, WA
SCALE	SHEET 5 OF 7	REV. B	LOCK, WA

Copyright © 2006 by DART AEROSPACE USA, INC.

PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

PURPOSE

욹


COPIED

봀

DOCUMENT

 $\overline{\mathbf{s}}$

W/O:			WORK ORDER CHANGES								
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
ļ											
	,										
 									1		
Part No	·	PAR #:	Fault Cat	egory:	NCR: Yes	No DQ	A:	Date: _			
	R	esolution:	Dispositi	on:	QA: N/C CI	osed:		Date: _			
NCR:		V	VORK ORE	DER NON-CONFORMA	NCE (NCF	R)			· ·		
DATE	STEP	Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval		
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		ion C	Chief Eng	QC Inspector		
		·									
									-		
				•							




۰ſ

Dart Aerospace L	_td
------------------	-----

W/O:			W	ORK ORDER CHANG	FS				
DATE	STEP	PRO	OCEDURE CH	100 100 100 100 100 100 100 100 100 100	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								Frod Wigi	
•									
•									
Part No	:	PAR #:	Fault Cate	egory:	_ NCR: Yes	No DO	QA:	Date: _	
	R	esolution:	Disposition	on:	_ QA: N/C (Closed: _		Date: _	
NCR:			WORK ORE	DER NON-CONFORMA	ANCE (NC	R)			
DATE	OTED	Description of NC			ion B	Verit	ication	Approvai	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	& Sec	ction C	Chief Eng	QC Inspector



DESIGN	DRAWN BY	DART	AEROSPACE USA, INC.
CHECKED	APPROVED/	DRAWING NO.	REV. B
		D3535	SHEET 7 OF 7
DATE		TITLE	SCALE
07.04.17		WEARSHOE	1:1



Copyright © 2006 by DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

W/O:			W	ORK ORDER CHANGES					
DATE	ATE STEP PRO			CEDURE CHANGE		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								Prod Wigi	
								:	÷
'									
Part No	•	PAR #:	_ Fault Cat	egory: I	NCR: Yes				
	R	esolution:	_ Dispositi	on:	QA: N/C CI				
NCR:		W	ORK ORE	DER NON-CONFORMAN	CE (NCR)			
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification		Approval	Approval
			Initial Chief Eng	Action Description Chief Eng	Sign & Date		ion C	Chief Eng	QC Inspector
						!			
				<i>,</i>					
								,	
				i,					
			:						
•									
I									